

**AGENDA of the
Portfolio Committee : Municipal Public Safety
19 May 2026
(Also the agenda for the Mayoral Committee Meeting : 26 May 2026)**

**2.
STATUS OF FIRE BRIGADE VEHICLES – 2025/2026 QUARTER 3**

**L Smith
20 April 2026**

Chief: Fire, Rescue & Disaster Management

(028) 313 5041

1. Executive Summary

The purpose of this report is to advise on the status of the fleet for Fire, Rescue & Disaster Management for period 1 January – 31 March 2026.

2. Service Delivery and Budget Implementation Plan - IGNITE

Directorate: Municipal Public Safety
Fire, Rescue & Disaster Management

3. Compliance with Strategic Priorities

Provision of democratic, accountable and ethical governance
Provision and maintenance of municipal services
Creation and maintenance of a safe and healthy environment

4. Delegated Authority

Executive Mayor

5. Legal Requirements

Constitution of the Republic of South Africa, 1996
SANS 10090: Community Protection Against Fires
Fire Brigade Services Act, Act 99 of 1987
Community Fire Safety By-law, P.N. 6454/2007
By-laws of Overstrand Municipality
Service Delivery Budget Implementation Plan

6. Background

The risk “Failure to provide/render effective fire and rescue service to the public, to fulfil constitutional mandate” was identified for inclusion in the risk register. One of the actions to be implemented was to report on a quarterly basis the status of the vehicles allocated to Fire, Rescue & Disaster Management.

Vehicles in the department must be prioritized for service delivery as the rendering of service of Fire Brigade personnel deal with damage to property and injuries as well as loss of property and possibly life.

**AGENDA of the
Portfolio Committee : Municipal Public Safety
19 May 2026
(Also the agenda for the Mayoral Committee Meeting : 26 May 2026)**

Fire Brigade vehicles are specialized vehicles with specific functions ie an aerial appliance (specialised vehicle with a ladder) will not be effective and efficient for a wildfire.

For an effective and efficient service, the correct fully equipped vehicle must be procured to render the service, with a reserve fleet for when vehicles are sent for annual maintenance or when breakages occur. Currently, when a vehicle is off-run it can take in excess of 3-months for the vehicle to be On-Run.

7. Financial Implications

In accordance with budget provision

8. Staff Implications

None

9. Comments from other Departments, Divisions and Administrations

None

10. Annexures

Annexure A: Status of Fire Brigade Fleet quarter 3

RECOMMENDATION:

that the status of Fire Brigade Vehicles – 2025/2026 for quarter 3 **be noted**.

RESPONSIBLE OFFICIAL :

L SMITH

TARGET DATE FOR IMPLEMENTATION :

TO BE NOTED

























Jan-26

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	Yes	No	
Alpha 1	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0	103%
Alpha 2	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	0	0	0%
Alpha 3	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0	103%	
Alpha 4	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	13	18	43%	
Alpha 7	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0	103%	
E1-1	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0	103%	
E2-1	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0	103%	
E3-1	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	11	20	37%	
Impi	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	0	31	0%	
P1	Y	Y	Y	Y	Y	Y	Y	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	7	24	23%	
P2	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0	103%	
P3	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	N	N	N	N	25	0	83%		
P4	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	0	31	0%	
P5	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0	103%		
P6	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	0	31	0%	
P7	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	14	17	47%		
T1	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	0	31	0%		
SV01	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	N	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	30	1	100%		
SV02	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	N	29	2	97%		
SV03	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0	103%		
SV04	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0	103%		
SV05	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	N	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	30	1	100%		
SV07	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0	103%		
SV08	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0	103%		
SV12(A5)	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	0	31	0%		
SV13 (A6)	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0	103%		
CV01	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	30	0	100%		
CV02	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0	103%		
CV03	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0	103%		
CV04	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0	103%		
CV05	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	0	31	0%		
Delta 1	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0	103%		













Feb-26















	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28							
Alpha 1	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y				28	0	<div style="width: 90%;"></div>	90%	
Alpha 2	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N				0	28	<div style="width: 0%;"></div>	0%
Alpha 3	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y				28	0	<div style="width: 90%;"></div>	90%	
Alpha 4	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N				0	0	<div style="width: 0%;"></div>	0%
Alpha 7	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y				28	0	<div style="width: 90%;"></div>	90%	
E1-1	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y				28	0	<div style="width: 90%;"></div>	90%	
E2-1	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y				28	0	<div style="width: 90%;"></div>	90%	
E3-1	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	N	Y	Y	Y	Y				27	1	<div style="width: 87%;"></div>	87%	
Impi	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N				0	28	<div style="width: 0%;"></div>	0%
P1	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N				0	28	<div style="width: 0%;"></div>	0%
P2	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y				28	0	<div style="width: 90%;"></div>	90%	
P3	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N				0	0	<div style="width: 0%;"></div>	0%
P4	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N				0	0	<div style="width: 0%;"></div>	0%
P5	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y				28	0	<div style="width: 90%;"></div>	90%	
P6	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N				0	28	<div style="width: 0%;"></div>	0%
P7	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N				0	28	<div style="width: 0%;"></div>	0%
T1	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N				0	0	<div style="width: 0%;"></div>	0%
SV01	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y				28	0	<div style="width: 90%;"></div>	90%	
SV02	N	N	N	N	N	N	N	N	N	N	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y				18	10	<div style="width: 58%;"></div>	58%	
SV03	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y				28	0	<div style="width: 90%;"></div>	90%	
SV04	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y				28	0	<div style="width: 90%;"></div>	90%	
SV05	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	28	0	<div style="width: 90%;"></div>	90%	
SV07	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	N	N	N	N	N	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y				23	5	<div style="width: 74%;"></div>	74%	
SV08	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y				28	0	<div style="width: 90%;"></div>	90%	
SV12	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N				0	28	<div style="width: 0%;"></div>	0%
SV13	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y				28	0	<div style="width: 90%;"></div>	90%	
CV01	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y				28	0	<div style="width: 90%;"></div>	90%	
CV02	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y				28	0	<div style="width: 90%;"></div>	90%	
CV03	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	N	N	N	Y	Y	Y				25	3	<div style="width: 81%;"></div>	81%	
CV04	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y				28	0	<div style="width: 90%;"></div>	90%	
CV05	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N				0	28	<div style="width: 0%;"></div>	0%
Delta 1	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	N	N	N	N	N	N	N	N	N	N	N	N	Y	Y	Y	Y	Y				16	12	<div style="width: 52%;"></div>	52%	

Mar-26








	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31				
Alpha 1	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0		103%
Alpha 2	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	16	0		53%
Alpha 3	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0		103%
Alpha 4	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	12	0		40%
Alpha 7	Y	Y	Y	N	N	N	N	N	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	26	5		87%	
E1-1	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0		103%	
E2-1	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0		103%	
E3-1	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	15	16		50%	
Impi	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	0	31		0%	
P1	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0		103%	
P2	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	15	0		50%	
P3	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	0	0		0%	
P4	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	0	0		0%	
P5	N	N	N	N	N	N	N	N	N	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	22	9		73%	
P6	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	0	31		0%	
P7	N	N	N	N	N	N	N	N	N	N	N	N	N	N	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	16	15		53%	
T1	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	0	31		0%		
SV01	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0		103%		
SV02	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0		103%		
SV03	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0		103%		
SV04	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0		103%		
SV05	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	0	0		0%		
SV07	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0		103%		
SV08	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0		103%		
SV12	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	0	31		0%		
SV13	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0		103%		
CV01	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0		103%		
CV02	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	N	N	N	N	N	N	N	N	N	N	20	11		67%		
CV03	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	N	29	2		97%		
CV04	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0		103%		
CV05	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	0	31		0%		
Delta 1	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	31	0		103%		









QUARTERLY OVERVIEW -AVAILABILITY BREAKDOWN PER VEHICLE

Alpha 1	 <p>99%</p>		<p>ON RUN Licence Expire</p>
Alpha 2	 <p>18%</p>		<p>OFF RUN</p>
Alpha 3	 <p>99%</p>		<p>On RUN</p>
Alpha 4	 <p>28%</p>		<p>On run</p>
Alpha 7	 <p>93%</p>		<p>OFF RUN Aircon</p>
E1-1	 <p>99%</p>		<p>ON RUN</p>

<p>E2-1</p>	 <p>99%</p>		<p>ON RUN</p>
<p>E3-1</p>	 <p>58%</p>		<p>OFF RUN Overheat, thermostat faulty. Repair Pump inlet and service pump</p>
<p>Impi</p>	 <p>0%</p>		<p>Purchase order issued (P/O) OFF RUN</p>
<p>P1</p>	 <p>42%</p>		<p>ON RUN</p>
<p>P2</p>	 <p>81%</p>		<p>OFF RUN</p>
<p>P3</p>	 <p>28%</p>		<p>OFF RUN Suspension issues and diff</p>
<p>P4</p>	 <p>0%</p>		<p>OFF Run awaiting DFFE documentation</p>

<p>P5</p>	 <p>89%</p>		<p>ON RUN</p>
<p>P6</p>	<p>0%</p>		<p>OFF RUN Clutch - engaging high and slipping under load. A fluid leak at the master cylinder could be causing the problem. Left Front Hub Seal - leaking seal at wheel hub Power Steering: fluid leaks from the hose. Hand Brake - ratchet mechanism not working/handbrake not functional</p>
<p>P7</p>	 <p>33%</p>		<p>ON RUN 4 x new tyres</p>
<p>T1</p>	<p>0%</p>		<p>OFF RUN - P/O issued, awaiting KANU registration issues Re-homologate category U fire engine Code 64 - with Kanu in PE</p>
<p>SV01</p>	 <p>98%</p>		<p>OFF RUN Check suspension and shocks</p>
<p>SV02</p>	 <p>86%</p>		<p>On Run</p>
<p>SV03</p>	 <p>99%</p>		<p>ON RUN - Damage rear light</p>

<p>SV04</p>	<p>99%</p>		<p>ON RUN</p>
<p>SV05</p>	<p>63%</p>		<p>OFF RUN</p>
<p>SV07</p>	<p>94%</p>		<p>ON RUN</p>
<p>SV08</p>	<p>99%</p>		<p>ON RUN</p>
<p>SV12</p>	<p>0%</p>		<p>OFF RUN</p>
<p>SV13</p>	<p>99%</p>		<p>ON RUN</p>
<p>CV01</p>	<p>98%</p>		<p>ON RUN</p>

<p>CV02</p>	 <p>74%</p>		<p>OFF RUN - Install, towbar, bumper and Canopy</p>
<p>CV03</p>	 <p>32%</p>		<p>OFF RUN 15 000km service</p>
<p>CV04</p>	 <p>34%</p>		<p>On RUN</p>
<p>CV05</p>	<p>0%</p>		<p>OFF RUN - Awaiting DFFE documents</p>
<p>Delta 1</p>	 <p>74%</p>		<p>ON RUN</p>