

**AGENDA of the
Portfolio Committee : Municipal Public Safety
19 August 2025
(Also the agenda for the Mayoral Committee Meeting : 26 August 2025)**

**3.
STATUS OF FIRE BRIGADE VEHICLES – 2024/2025 QUARTER 4**

**NJ Michaels
14 July 2025**

Director: Municipal Public Safety

(028) 313 8054

1. Executive Summary

The purpose of this report is to advise on the status of the fleet for Fire, Rescue & Disaster Management for period 1 April – 30 June 2025.

2. Service Delivery and Budget Implementation Plan - IGNITE

Directorate: Municipal Public Safety
Fire, Rescue & Disaster Management

3. Compliance with Strategic Priorities

Provision of democratic, accountable and ethical governance
Provision and maintenance of municipal services
Creation and maintenance of a safe and healthy environment

4. Delegated Authority

Executive Mayor

5. Legal Requirements

Constitution of the Republic of South Africa, 1996
SANS 10090: Community Protection Against Fires
Fire Brigade Services Act, Act 99 of 1987
Community Fire Safety By-law, P.N. 6454/2007
By-laws of Overstrand Municipality
Service Delivery Budget Implementation Plan

6. Background

The risk “Failure to provide/render effective fire and rescue service to the public, to fulfil constitutional mandate” was identified for inclusion in the risk register. One of the actions to be implemented was to report on a quarterly basis the status of the vehicles allocated to Fire, Rescue & Disaster Management.

Vehicles in the department must be prioritized for service delivery as the rendering of service of Fire Brigade personnel deal with damage to property and injuries as well as loss of property and possibly life.

**AGENDA of the
Portfolio Committee : Municipal Public Safety
19 August 2025
(Also the agenda for the Mayoral Committee Meeting : 26 August 2025)**

Fire Brigade vehicles are specialized vehicles with specific functions ie an aerial appliance (specialized vehicle with a ladder) will not be effective and efficient for a wildfire.

For an effective and efficient service, the correct fully equipped vehicle must be procured to render the service, with a reserve fleet for when vehicles are sent for annual maintenance or when breakages occur. Currently, when a vehicle is off-run it can take in excess of 3-months for the vehicle to be On-Run.

7. Financial Implications

In accordance with budget provision

8. Staff Implications

None

9. Comments from other Departments, Divisions and Administrations

None

10. Annexure

Annexure A: Status of Fire Brigade Fleet quarter 4

RECOMMENDATION:

that the status of Fire Brigade Vehicles – 2024/2025 for quarter 4 **be noted.**

RESPONSIBLE OFFICIAL :


NJ MICHAELS

TARGET DATE FOR IMPLEMENTATION :











TO BE NOTED








Jun-25















	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
Alpha 1	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
Alpha 2	Y	Y	Y	Y	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N
Alpha 3	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
Alpha 4	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
Alpha 7	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N
E1-1	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
E2-1	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
E3-1	Y	Y	Y	Y	Y	Y	Y	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N
P1	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N
P2	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
P3	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N
P5	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
P6	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
P7	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N
SV01	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
SV02	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
SV03	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
SV04	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
SV05	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
SV07	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
SV08	Y	Y	Y	Y	Y	Y	Y	Y	Y	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N
SV12	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N
SV13	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N
CV01	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CV02	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CV03	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
CV04	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
Delta 1	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N

















QUARTERLY OVERVIEW - AVAILABILITY BREAKDOWN PER VEHICLE

Alpha 1	 <p>88%</p>		<p>ON RUN</p> <p>-Diesel pump & black smoke, handbrake light, clutch, Pump Faulty</p>
Alpha 2	 <p>67%</p>		<p>ON RUN</p> <p>-Diesel pump & black smoke, handbrake light, clutch, Pump Faulty</p>
Alpha 3	 <p>98%</p>		<p>OFF RUN</p> <p>Oil leak, alternator light</p>
Alpha 4	 <p>88%</p>		<p>ON RUN</p>
Alpha 7	 <p>63%</p>		<p>OFF RUN</p> <p>Since Aug 2026</p>
E1-1	 <p>100%</p>		<p>ON RUN</p> <p>Planned service due</p> <p>Vehicle Service due, and both hoses faulty, Cracked Windscreen, Window winders, crew cab door knips, Front R light, R side step</p>

E2-1	100%		ON RUN
E3-1	66%		OFFUN - Annual service and repairs approve awaiting ST Motors
P1	11%		Await registration
P2	100%		On Run
P3	18%		ON RUN Vehicle Service due
P5	100%		ON RUN Vehicle Service due
P6	100%		ON RUN Vehicle Service due

P7	 <p>7%</p>		ON RUN OLD Lady
SV01	 <p>92%</p>		ON RUN
SV02	 <p>100%</p>		ON RUN
SV03	 <p>61%</p>		On Run
SV04	 <p>100%</p>		ON RUN - Damage L light
SV05	 <p>99%</p>		ON RUN
SV07	 <p>100%</p>		On Run

SV08	 <p>77%</p>		On Run
SV12	 <p>0%</p>		ON RUN
SV13	 <p>0%</p>		OFF RUN DIFF
CV01	 <p>100%</p>		ON RUN
CV02	 <p>91%</p>		ON RUN Branding done
CV03	 <p>31%</p>		ON RUN Branding done
CV04	 <p>32%</p>		ON RUN Branding done

